

NONCOMPLIANCE REPORT

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

February 2020 – The first week's effluent arsenic sample was in compliance and then there was a slight bump to 13 ug/L but the last week's sample went down to 11 ug/L.

March 2020 – Although the five weeks of effluent samples were slightly over 10 ug/L, ranging from 11 ug/L to 14 ug/L, they were still less than the baseline sample of 28 ug/L.